

Application Data Sheet

Application Information

Application number::	Not Yet Assigned
Application Type::	Regular
Subject Matter::	Utility
Suggested Group Art Unit::	N/A
CD-ROM or CD-R?::	None
Sequence submission?::	None
Computer Readable Form (CRF)?::	No
Title::	METHOD FOR DIAGNOSING INCORRECT VALVE LIFT ADJUSTMENT IN AN INTERNAL COMBUSTION ENGINE
Attorney Docket Number::	449122058100
Request for Early Publication?::	No
Request for Non-Publication?::	No
Small Entity?::	No
Petition included?::	No
Secrecy Order in Parent Appl.?::	No

Applicant Information

Applicant Authority Type::	Inventor
Primary Citizenship Country::	Germany
Status::	Full Capacity
Given Name::	Frank
Family Name::	WEISS
City of Residence::	Grasslfing
Country of Residence::	Germany
Street of mailing address::	Igelbergweg 5
City of mailing address::	Pentling/Grasslfing
Country of mailing address::	Germany
Postal or Zip Code of mailing address::	93080

Applicant Authority Type:: Inventor
Primary Citizenship Country:: China
Status:: Full Capacity
Given Name:: Hong
Family Name:: ZHANG
City of Residence:: Tegernheim
Country of Residence:: Germany
Street of mailing address:: Spitzweg Straße 16
City of mailing address:: Tegernheim
Country of mailing address:: Germany
Postal or Zip Code of mailing address:: 93105

Correspondence Information

Correspondence Customer Number:: 25227

Representative Information

Representative Customer Number:: 25227

Foreign Priority Information

Country:	Application number:	Filing Date:	Priority Claimed:
Germany	10230899.3	07/09/02	Yes